TC11: Painting, Intumescent, and	

Spray Fireproofing	Wenrich Painting				Paint Ninjas, Inc.				
Generated October 1, 2024	Submitted by Estimating Department @Wenrich Painting				Submitted by Jason Halterman				
Base Bid	\$465,660			\$627,000					
	Original Proposal, September 26, 202	24			Original Proposal, September 26, 2024	4			
LINE ITEMS	Unit	Qty	Unit Cost	Total Cost	Unit	Qty	Unit Cost	Total Cost	
Painting, Intumescent, and Spray Fireproofing				\$465,660				\$627,000	
ALTERNATES Alternate #1: In lieu of new windows, refurbish				\$0				\$0	
existing windows in-situ. Replace existing solid panels and louvers in transoms with glass lites. Remove interior screens. Fix existing sash in place with perimeter sealant and mechanical fasteners. Remove all existing hardware and									
provide plugs to fill holes. Replace all exterior sealant.				\$0				\$0	
Alternate #2: Remove zinc-tin alloy coated copper metal roof (per specification sections 07 6100 and 076200) and replace with aluminum standing seam metal roof.				\$0				\$0	
Alternate #3: Remove slate roof (per specification section 07 3126) and replace with standing seam aluminum roof.				\$0				\$0	
Alternate #4: NOT USED				\$0				\$0	
Alternate #5: NOT USED Alternate #6: Remove sound absorbing ceiling panels (SAP-1) (per specification section 09				\$0				\$0	
430) from all corridors (Q001, Q202, Q203, Q204, Q302, Q303, Q304) at Sub-Basement Level, Level 2, and Level 3 and paint existing exposed structure.TC09				\$0				\$4,675	
Alternate #7: Remove resinous matrix terrazzo flooring and terrazzo base at all locations and replace with cementitious floor topping (per specification section 03 5446) and wood base (per specification section 06 4023).				\$0				\$0	
Alternate #8: Remove cementitious floor topping at L2 (per specification section 03 5446) and replace with resinous matrix terrazzo flooring and terrazzo base (per specification section 09 6623). Include appropriate underlayment for resinous matrix terrazzo flooring.				\$0				\$0	
Alternate #9: Remove cementitious floor topping at L2, L3 and L4 (per specification section 03 5446) and replace with resinous matrix terrazzo flooring and terrazzo base (per specification section 09 6623). Include appropriate underlayment for resinous matrix terrazzo flooring.				\$0				\$0	
Alternate #10: Remove southeast areaway scope as shown on Drawings A6.30 and A6.31 and infill areaway as shown on drawing 12/A6.21.				¢0.				¢0.	
Alternate #11: Remove wood benches (per specification section 06 4023) at corridors Q101 and Q102.				<u>\$0</u> \$0				\$0 \$0	
Alternate #12: Install alternate sanitary sewer system as depicted on sheet C0.09. Any water pumped from utility trenches shall be directed to a sediment removal facility, such as a filter bag or approved equal. Only trenching work that can be completed and permanently stabilized each working day shall be performed in order to prevent sediment laden runoff from leaving the site. Immediately repair any BMP after installation of the sanitary sewer. Sanitary Sewer shall be steel encased and bord beneath steam									
tunnel when crossing. Scope Specific Alternate #1: Provide one				\$0				\$0	
additional coat of paint on all interior walls.				\$72,998				\$42,932	
Base Bid Total				\$465,660				\$627,000	
SCOPE-SPECIFIC INFORMATION									
Unit Cost Add: Per square foot of existing concrete sandblasting	per square foot			\$0.00	per square foot			\$0.00	
Unit Cost Deduct: Per square foot of existing concrete sandblasting	per square foot			\$0.00	per square foot			\$0.00	
Include total number of labor hours for all on site personnel including subcontractors.	NA				0				

